



# Car Seat Recalls/Defects & Safety Notices – Archive 2018

This list covering child car seats manufactured after 12/31/08 is a publication of the Washington State Safety Restraint Coalition 1-800BUCKLUP ([www.800BUCKLUP.org](http://www.800BUCKLUP.org)). The National Highway Traffic Safety Administration & child restraint manufacturers do not recommended using restraints older than six to ten years based on the type of seat. This list contains older seats as a reference document. Information may change, always call manufacturer to verify.

**Alkot** (see Love Seat)

## All Our Kids (Out of business)

**Travel Vest:** All models **Problem:** Fails flammability. **Destroy!**

**American Motors** (See Love Seat)

## Babyhood (out of business)

### Convertible Seats

**Baby-Sitter** Model 8200 made 1/92-6/93. **Problem:** Buckle can be hard to release. **Destroy!**

**Wonda Chair** Model 810 pre-12/82. **Problem:** Harness may be misrouted. **Destroy!**

## Baby Trend

800-328-7363, [www.babytrend.com](http://www.babytrend.com)

### Infant Seats

**Rigid Latch-Loc** Models 6439, 6448, 6481, & stand alone base 6400 made 5/14/07-4/1/08. **Problem:** LATCH connector metal parts (pawls) can crack allowing connectors on base to release from vehicle anchors in severe crash. **Call:** 800-328-7363 for replacement Flex-Loc Base in exchange for Rigid Latch-Loc Base. Until replaced secure base or seat alone w/ vehicle belt.

**Basic Comfort** (Out of Business)

### Booster Seats

**Galaxy 2000** All models **Problem #1:** Improperly positioned shoulder belt may increase risk of injury. **Destroy!** **Problem #2:** Made 11/25/98-1/31/99. Defective backs & cushions may become brittle. **Destroy!**

**Bobby Mac** (see Evenflo)

## Bolform (out of business)

**Buckle Up** Model 84E-019 **Problem:** Failed crash test. **Destroy!**

**Britax** 888-427-4829,

[www.britaxusa.com](http://www.britaxusa.com)

### Infant Seats

**Companion Problem #1:** All Models made pre-11/1/07. Clarification campaign to update users guide; clarify height; & inner buckle strap position. Use inner buckle position for infants under 11 lbs. Once child reaches 11 lbs. move to outer position for remainder of use with that child. Child exceeds height requirement when top of head is less than 1 inch from top of seat or height exceeds 30 inches. **Call:** 888-427-4829 for instructions & labels.

**Problem #2:** Model E9L14 made 10/31/03-6/6/04. Tabs on bottom of carrier may not be properly seated. If not properly seated carrier may rotate too far in crash increasing risk of injury. **Call:** 888-427-4829 for inspection instructions. If unit is affected, use carrier without base until replaced. Britax recommends use of this product be discontinued as it is older than six years from date of manufacture.

### Convertible Seats

**Advantage** model E9022 made 3/5/01-7/26/01. **Problem:** Tether bracket may separate from seat in crash. **Destroy!**

**Boulevard** Model beginning E9L57 made 3/1/06-8/1/06. **Problem:** In crash, tether hook may open/break & release when used forward facing for child over 50 lbs. If tether breaks, seat may move from upright to reclined position increasing risk of injury. Do not use tether for child over 50 lbs. **Call:** 888-427-4829 for new manual & labels.

**Decathlon** Model E9L47 made 2/12/05-7/31/07. **Problem:** When adjuster strap is pulled from an extreme side angle, push button housing may separate from shell. Allowing adjuster to move out of position so harness may become difficult to tighten properly. **Call:** 888-427-4829 to request push rivet fasteners to secure adjuster to housing.

**Marathon Problem #1:** Model E9L06, E9W06 & E906 made 5/23/06-7/28/06. Only seats with lot number "KGR 01 A" stamped on tether hook are affected. Tether hook may open

& release, when used for a child weighing more than 50 lbs, allowing child to move too far forward. Discontinue use of tether for child over 50 lbs until replacement is installed. **Note:** Tether should only be used beyond 50 lbs if vehicle manufacturer allows tethering above this weight. **Call:** 888-427-4829 for tether hook & "DO NOT USE" label. **Problem #2:** Model E9L06 made pre-7/24/04. Adjustment strap may slip & allow harness to loosen. **Call:** 888-427-4829 for new strap. Until replaced, check slippage by pulling on harness without lifting release lever. If harness loosens do not use seat until fixed.

**Roundabout** Model 161 made 1/13/99-3/14/99. **Problem:** Shell may be molded incorrectly allowing too much forward head movement. **Destroy!**

**Wizard** Model E9L07 made pre-7/24/04. **Problem:** Adjustment strap may slip & allow harness to loosen. **Call:** 888-427-4829 for new strap. Until replaced, check slippage by pulling on harness without lifting release lever. If harness loosens do not use seat until fixed. Britax recommends use of this product be discontinued as it is older than six years from date of manufacture.

### Forward Facing Only Seats

**Husky Problem #1:** Model E9L30 made pre-7/24/04. Adjustment strap may slip & allow harness to loosen. **Call:** 888-427-4829 for new strap. Until replaced, check slippage by pulling harness without lifting release lever. If harness loosens do not use seat until fixed. Britax recommends use of this product be discontinued as it is older than six years from date of manufacture. **Problem #2:** All models & manufacture dates. Use of long (serpentine) belt path w/ lap only belt allows too much forward head movement. **Call:** 888-427-4829 for new labels & instructions.

**Regent Advisory Problem #1:** Models beginning E9L39 made pre-6/18/07. Seat & instructions have been modified to enhance performance. **Call:** 888-427-4829 for instructions, label, longer LATCH strap & slip-resistant strips. Use long belt path for 22-40 lbs. & short path for 40-80 lbs. Recline bar required for

ALL installations. **Problem #2:** Recall model E9L3998 made 12/18/06-1/18/07 with Classic fabric. Incorrect warning label on cover. **Call:** 888-427-4829 for new pad.

**Traveler Plus** Model E9L32 made pre-7/24/04. **Problem:** Adjustment strap may slip & allow harness to loosen. **Call:** 888-427-4829 for new strap. Until replaced, check slippage by pulling on harness without lifting release lever. If harness loosens do not use seat until fixed. Britax recommends use of this product be discontinued as it is older than six years from date of manufacture.

### Combination Seats

**Frontier** Model E9L54E7, E9L54H6, E9L54H7, & E9L54M6 (black harness) made 4/1/08-9/14/08, and E9L5490 (beige harness) made 4/1/08-9/17/08. **Problem:** When loosening harness by pulling on only one strap, straps may become detached from harness yoke on back of seat causing child to be improperly restrained. **Call:** 888-427-4829 for repair kit with plastic covers for end of harness. Always pull on both straps to loosen.

### Forward Facing Only Seats

**Freeway** model 101 made 6/1/96-4/18/97. **Problem:** Buckle can be opened by lifting up on push button. **Destroy!**

**Super Elite Problem #1:** Model E9031 all dates. Harness adjuster may stick causing webbing to slip & harness to loosen. **Call:** 888-427-4829 for adjuster strap guide. Until repaired check harness is secure before use. **Problem #2:** Model E9031 made 4/25/01-2/15/02. Too much forward head movement in crash without HUGS harness system. **Destroy!**

**Century** (see Graco)

**Champion** (see Renolux)

## Chicco

877-424-4226 [www.chiccousa.com](http://www.chiccousa.com)

### Infant Seats

**KeyFit & KeyFit 30 Bases Only** All models made 2/26/08-3/17/08. **Problem:** Some bases have defect in



LATCH attachments. When installed with LATCH webbing used to tighten seat, can slip & loosen. **NOTE:** Until repaired install only with vehicle seat belt. **Call:** 800-807-8817 to report defective base and receive envelope. Owner will then cut off LATCH connectors, send in with personal information and will receive new base.

## Chrysler

### Built-In Child Seats

**Minivan Integrated Seat** Made 6/96-7/96. **Problem:** Bolts holding seat to frame can break. **Call:** dealer for replacement.

### Town & Country, Dodge

**Caravan/Grand Caravan, Plymouth Voyager/Grand Voyager Integrated Seat.** Made 1996-97. **Problem:** Latch plate becomes dirty making harness release difficult. **Call:** dealer to clean & add emergency release extender.

**1998 Dodge Caravan & Grand Caravan; Plymouth Voyager, Grand Voyager, & Town & Country.** **Problem:** Shoulder harness webbing may be incorrectly routed & fail in crash. **Call:** dealer for inspection/correction of threading.

## Collier Keyworth

### (Out of business)

**Safe & Sound II** made 12/28/84-4/3/85. **Problem:** Buckle fails (single tongue, no writing on back). **Destroy!**

## Combi USA, Inc.

800-992-6624 www.combiusa.com

### Infant Seats

**Centre & Centre ARB** Model 8065, 8074, 8086, 8087 & 8520 made 10/2005-12/2007. **Problem:** Seat may separate from base in frontal crash. **Call:** 800-543-7734 for retrofit kit. Until installed, use only without base.

**Shuttle** Model 4400, 4515, & 4520 made 10/2005-12/2007. **Problem:** Seat may separate from base in frontal crash. **Call:** 800-543-7734 for retrofit kit. Until installed, use only without base.

### Convertible Seats

**Avatar** Model 8100 made 11/03-5/04. **Problem:** Lower LATCH belt does not meet standards. In crash seat may detach from lower anchorage resulting in serious injury. **Call:** 800-992-6624 until kit is installed, do NOT use LATCH to install use vehicle seat belt instead.

## Dorel Juvenile Group (Cosco, Maxi-Cosi, Safety 1<sup>st</sup>, Quinny, and Eddie Bauer)

800-544-1108, www.djgusa.com

### Car Beds

**Dream Ride** Model 02-719 (w/ blue/pink plaid cover) made 1/89-1/11/94. **Problem:** Cover not flame retardant. **Destroy!**

**Dream Ride Ultra** Model 02-719 made 4/94-6/95. **Problem:** Seat rotates too far forward in crash. **Destroy!**

**Dream Ride Ultra** Model 22-001FSM made 12/01/03-4/28/04. **Problem:** Failed testing when used rear-facing. Use only as car-bed. **Call:** 866-611-3022 for warning label. If child needs rear-facing seat, Dorel will replace.

### Infant Seats

**Arriva Problem #1:** Models begin "02-" 665, 729, 731, 732, 733, 751, 756, & 757 made 3/1/95-9/9/97. Handle releases suddenly when carried seat may flip & child may fall. **OR Problem #2:** 02-751 DDF or MMF made 3/1/95-5/31/95. Latch release button & spring may separate when button is pushed. **OR Problem #3:** Model 02-729TED made 3/31/99-4/7/99 **OR Problem #4:** Missing air bag warning label. **Problems 1-4: Destroy!**

**Arriva & Turnabout** Models begin "02-" 665, 727, 728, 729, 731, 732, 733, 750, 751, 755, 757, 774, 753, 756, 758, 759, 760, 761, 762, 763, 764, 765, 770, 771, & 772 made pre-1/31/00. **Problem:** Handle releases suddenly when carried seat may flip & child may fall. **Destroy!**

**Comfort Problem #1:** Models begin "22-" 331 BLA, 332 RLA, 631 LNC, 630 AFD, 630 BAL, 630 FMT, 630 HPN, 630 LRS, 630 LKM & 630 MRC made 7/26/05-2/28/06. Handle trim screws can loosen presenting choking hazard. **Call:** 877-229-1374 or <http://comfortinfant.djgusa.com> for repair kit. **Problem #2:** Models beginning "22-" 331, 332, 630, & 631. Some consumers experience difficulty installing the original base. **Call:** 877-229-1374 for replacement base under this Customer Satisfaction Program or visit <http://comfortinfant.djgusa.com>.

**Designer 22 Problem #1:** Models 02-621-SAL, 02-620-AZY, & 02-620-BEA made 1/3/02-2/13/02. **Problem #1:** Handle releases suddenly when carried seat may flip & child may fall. **Destroy! Problem #2: Designer 22** Models all begin "22-" & end "GB1B" - 625 AFD, 625 GLC, 625 EDG, 625 MAC, 325 CMB, 325 VIN, 325 DTA, 325

TST, & 300JOS made 8/19/03-10/20/04. **Problem:** If harness isn't properly tightened, webbing may slip, in crash child could move too far forward increasing risk of injury. **Destroy!**

**Maxi Cosi Mico Problem:** Models 22-371, 22-372, & Separate Base 22-515 made 7/1/07-6/28/08. **Problem:** Carrier may not attach properly to base. If carrier is not properly attached child could be injured in crash. Until fixed check connection by pulling up on carrier to assure engagement with base. **Call:** 877-657-9546 or visit safety notices at [www.djgusa.com/safety\\_notice](http://www.djgusa.com/safety_notice)

**Turnabout** Models begin "02-" 667, 758, 759, 760, 761, 762, 763, 764, & 765. made 3/1/95-9/9/97. **Problem:** Handle releases suddenly when carried seat may flip & child may fall. **Destroy!**

**Voyager (w/ stroller)** made 9/8/97-10/27/97. **Problem:** When used in stroller carrier may dislodge & fall. **Destroy!**

### Convertible Seats

**Alpha Omega & Eddie Bauer 3-in-1** Models 02-332, 02-531, 02-533, 02-537 & 02-555 made 1/1/00-9/30/01. **Problem:** Tether webbing fails abrasion test increasing risk of injury to child in a crash. **Destroy! Problem #2:** Models 02-331, 02-332, 02-531, 02-533, 02-537, & 02-555. Made 11/17/00-1/10/01. Tether webbing may be cut & separate in crash increasing risk of injury. **Destroy!**

**Alpha Omega, Alpha Omega Elite, 3-in-1, Deluxe 3-in-1, Deluxe Convertible, Alpha Elite, Intera & Enspira** Models begin "22-" 150, 151, 155, 180, 250, 269, 450, 451, 452, 453, 455, 460, 480, 481, 740, 755, 756, 757, & 770 made 11/03-12/05. **Problem:** Harness adjuster may slip increasing risk of injury in crash. Check for slippage: tighten harness, pull harness straps without pressing/lifting adjustment lever. If movement occurs, use different seat until fixed! **Call:** 800-219-0509 for kit.

**Alpha Omega & Eddie Bauer 3-in-1 Problem #1:** Models 22-150, 22-151, & 22-770. Made 10/1/05-12/31/05. **Problem:** Child's fingers may get caught in hole in edge of armrest shell. **Call:** 877-639-0659 for repair of voluntary safety notice.

**Regal Ride** Model 22-139 MON. **Problem:** Made 9/28/04-9/20/07. Elastic straps securing fabric pad to seat shell may come loose allowing child to loop strap around body. **Call:** 888-698-6681 for repair kit.

**Touriva or Eddie Bauer Touriva** Models 22-100 TTD, 22-100 FSM, 22-

100 TIP, 22-111 FSM, 22-130 WAL, 93-100 FSM, & 93-111 FSM. Made 9/28/04-9/20/07. **Problem:** Elastic straps securing pad to seat shell may come loose allowing child to loop straps around body. **Call:** 888-698-6681 for repair kit.

**Deluxe Commuter Tray Shield** model 02-086 made 11/1/87-2/10/88. **Problem:** Exposed foam is choking hazard. **Destroy!**

**Safe-T-Shield** Models 81A, 81B, 181A, 181B (w/ metal pull knobs) made 1/81-6/83. **Problem:** Push-pin holding shield may break making child difficult to remove. **Destroy!**

**Safe-T-Mate** Made 1984. **Problem:** Instructions show wrong rear-facing belt placement. **Destroy!**

**Safe & Easy 313; Safe & Snug 323 & Luxury Safe & Snug 423.** Made 1/84-6/85. **Problem:** Cracks appear where frame attaches to shell. **Destroy!**

**Soft Shield: Soft Shield** 02-090 & **Soft Shield Deluxe** 02-190, **Auto Trac** 02-290, **Luxury** 02-790 & 02-890 Made 10/89-6/90. **Problem:** Child's head goes too far forward. **Destroy!**

**Touriva 5-pt.** Models 02-514, 02-584, & 02-518 **Problem:** Made 8/9/97-8/22/97 w/ mold #3" on top back of shell (may need to remove locking clip on seat back to see number). Belt path in shell may weaken when used in forward-facing reclined position. **Destroy!**

**Touriva or Eddie Bauer Touriva Problem #1:** Models 02-514FSM, 02-519OXF, 02-524AAR, 22-100TTD, 93-446FSM & 93-504BHO. Made 3/15/02-8/1/02. Harness may not be adequately protected it from deterioration from sunlight. **Destroy! Problem #2:** Models 02-014, 02-015, 02-019, 02-084, 02-094, 02-114, 02-504, 02-514, 02-518, 02-519, 02-524, 02-584, 02-803, 02-806, 02-821, 02-825, 02-870, 02-871, 02-875, 02-935, 93-084, 93-094 & 93-514. Made 1/1/00-9/30/01. Tether webbing fails abrasion test increasing risk of injury to child in a crash. **Destroy!**

**Touriva Overhead-Shield** Models 02-014 & 02-015 Made 8/9/97-8/22/97 w/ mold #3" on top back of shell (may need to remove locking to see number). **Problem:** Belt path may weaken when used in forward-facing reclined position. **Destroy!**

**Touriva Safe T-Shield Problem #1:** models 02-084, 02-096, 02-404, 02-094 & 02-821. Made 5/1/96-11/26/97. Buckle release is difficult. **Destroy! Problem #2:** model 02-084 made 5/6/94-8/10/94. Buckle may break & harness can loosen. **Destroy!**



## Combination Seats

### High Back or Eddie Bauer High Back Problem #1:

Models beginning "02" 409, 442, 443, 445, 448, 449, 450, 480, 495, 849 & 880 made 1/1/00-9/30/01. Tether webbing fails abrasion test increasing risk of injury to child in a crash. **Destroy!** **Problem #2:** Model 02-442CNG, 02-442DNP, 02-442JUB, 02-443PRI, 02-448BNG, 02-848BNG, 93-443PRI, & 93-514FSM. Made 3/15/02-8/1/02. Harness may not be adequately protected it from deterioration from sunlight. **Destroy!**

### Booster Seats

**High Rise** Model 22-297, 22-298, & 22-299. Made 10/1/03-10/31/03. **Problem:** Warning label on side of seat states restraint is for use by children UNDER 1 year. **Destroy!**

## Early Development

(Out of Business) (No Recalls)

## Evenflo

800-233-5921, [www.evenflo.com](http://www.evenflo.com)

### Infant Seats

**All Cozy Carry Bases. Problem:** Performance of base may be improved in certain crashes. **Call:** 800-233-5921 for upgrade kit.

**Discovery Problem #1:** Model 3021769Z & 3021854Z. Made 2/4/08. (All sold at Target & Wal-Mart Stores.) Seat may have shipped without complete assembly of red release handle. Under certain conditions, this may cause seat to separate from base resulting in serious injury. **Call:** 800-233-5921 for replacement seat & base. Until replaced install seat only without base. **Problem #2:** Models beginning 390, 391, 534, & 552. Made 4/1/05-1/31/08. Seat could separate from base in high impact side crash. **Call:** 800-356-2229 for dual hook fastener.

**Dyn-O-Mite Problem #1:** models 441, 446 & 448 w/ tubular steel frame made pre-2/89. Exceeds safe angle in most reclined position. Thread shoulder belt through clip on seat back. If only lap belt, use only in first three positions. **Destroy!** **Problem #2:** models 202, 441-446 & 448 made 4/15/85-4/22/90. Black buckle seems secure when not fully latched. **Destroy!**

**Embrace** Models beginning 317, 320, 397, 398, 540, 548, 549, 550, 556, 597, 598, & 599. Made pre-4/8/06. **Problem:** Handle releases unexpectedly when carried. May allow seat to flip & child to fall. **Call:** 800-490-7497 for repair kit. Do not

use handle to carry until installed.

**Infant Seat Problem #1:** Models 456 & 458 made pre-4/10/89. Exceeds safe angle in most reclined position. Thread shoulder belt through plastic clip on seat back. If only lap belt, use seat only in first position. **Destroy!** **Problem #2:** models 456 & 458 made 4/15/85-4/22/90. Black buckle seems secure when not fully latched. **Destroy!**

**Joy Ride** all models **Problem:** When used w/ base see Travel Tandem recall below. **Problem #2:** models 203, 205, 210, 435, & 493 made 1/1/88-12/31/98. Handle releases suddenly when carried causing seat to flip & unbuckled child to fall. Do not use as carrier! **Destroy!**

**On My Way & Travel System car seat/stroller. Problem #1:** models 207 & 492 made 12/15/95-7/27/97. Handle releases unexpectedly when carried causing seat to flip & child to fall. Do not use as carrier! **Problem #2:** model 206 made 5/7/94-5/31/95. Cracks develop on shell. **Problem #3:** All seats w/ Position Right Bases see #2 above. **Problems 1-3 Destroy!**

**All Seats w/ Position Right Bases. Problem:** ALL models Made pre-2/10/00. Posts may bend making seat difficult to attach to base. **Destroy!**

**SecureRide** model 626 made 8/15/94-3/17/95. **Problem:** Air bag label improperly placed. **Destroy!**

**Travel Tandem (Joy Ride w/ base)** Made 9/1/93-3/31/96. **Problem:** When tested w/ base, shell broke & seat released from base. Do not use base! **Destroy!**

### Convertible Seats

**410** made 6/88-4/89. **Problem:** Ejection of child. **Destroy!**

**Bobby-Mac Champion 411; Bobby-Mac Deluxe 412, 414, 415** made 4/15/85-4/22/90 **Problem:** Black buckle seems secure when not fully latched. **Destroy!**

**Champion/Trooper/Scout 5-Pt. Problem #1:** model 229 made 6/1/93-12/16/96. Increased risk of injury in crash. **Destroy!** **Problem #2:** Made 10/14/96-2/6/97. Too much forward movement. **Destroy!**

**Champion/Trooper/Scout T-Shield** model 225 made 10/14/96-2/6/97. **Problem:** Too much forward movement. **Destroy!**

**Champion/Trooper/Scout Tray Shield** model 224. **Problem #1:** made 2/8/93-8/4/93. Harness sleeve makes buckling difficult. **Problem #2:** made 6/1/93-11/22/96. Increased risk of chest injury. Use only in reclined position. **Problem #3:** made 10/14/96-2/6/97. Too

much forward movement increases risk of head injury. **Problems 1-3 Destroy!**

**Champion/Trooper/Scout Adjust-A-Shield** model 219. **Problem #1:** made 11/27/95-1/22/96. Toddler section of instructions labeled for Infant use, causing user to believe Infants under 20 lbs. can ride forward-facing. **Destroy!** **Problem #2:** made 10/14/96-2/6/97. Too much forward movement. **Destroy!**

**Guardian T-Shield** models 634, 643, 653, 654 & 655 made 1/31/90-5/3/90 **Problem:** Buckle release too easy. **Destroy!**

**One Step & One Step Deluxe** models 401-409 & 223 made 4/15/85-4/22/90 **Problem:** Black buckle seems secure when not fully latched. **Destroy!**

**Seven Year Problem #1:** models 453 & 454 made 2/13/87-10/31/88. Pins present choking hazard. **Destroy!** **Problem #2:** models 453, 454, & 228 made 4/15/85-4/22/90. Black buckle seems secure when not fully latched. **Destroy!**

**Tribute & Tribute 5** Models beginning with 378 or 379 made 9/8/05-9/22/05. **Problem:** Shell may crack in some types of crashes. **Call:** 800-233-5921 for replacement.

**Triumph** Models 264, 359, & 389 made 9/6/01-10/31/05. **Problem:** Child may pull back cloth cover accessing foam liner becoming choking hazard. **Call:** 800-490-7591 for protective sleeve upgrade kit.

**Triumph Problem #1:** model 264 made 10/20/01-1/31/02. The slide loop connectors holding harness may not be strong enough to properly restrain child. **Destroy!** **Problem #2:** model 264, 359, & 389 made 9/6/01-10/31/05. Child may pull back cloth cover accessing foam liner becoming choking hazard. **Call:** 800-490-7591 for protective sleeve upgrade kit.

**Ultara I Problem #1:** model 420 made 9/22/88-7/1/89. Buckle hard to unlatch. **Destroy!** **Problem #2:** model 231 made 2/8/93-8/4/93. Harness sleeve makes buckling difficult. **Destroy!**

**Ultara II Problem #1:** model 232 made 2/8/93-8/4/93. Harness sleeve makes buckling difficult. **Destroy!** **Problem #2:** model 227 made 1/5/90-6/90. Too much forward movement. **Destroy!**

### Combination Seats

**Two-in-One** models 636 & 637 made 1/7/98-3/20/98. **Problem:** Back & seat base separate when used w/ harness. **Destroy!**

### Booster Seats

**Sidekick** model 244 made 4/23/96-

5/20/97. **Problem:** Shield allows too much forward movement increasing risk of injury. **Destroy!**

**Small Shield Problem #1:** models 470 & 471 made 2/13/87-10/31/88. Pins on pad present choking hazard. **Call:** 800-233-5921. **Problem #2:** models 471, 242 made 4/15/85-4/22/90. Black buckle seems secure when not fully latched. **Destroy!**

## F.B.S. (See Renolux)

## Fisher Price

(No longer makes Car Seats)  
800-432-5437 [www.fisher-price.com](http://www.fisher-price.com)

### Infant Seats

**Model 9149** made 1/1/91-2/27/91. **Problem:** Shield can separate. **Destroy!**

**Model 9173** made 9/1/94-10/31/94. **Problem:** Air bag warning label can not be seen when in front seat. **Destroy!**

### Convertible Seats

**Safe Embrace** model 79700 made 5/19/97-3/29/98. **Problem:** Harness adjuster spring can break/dislodge. If it fails, harness may not lock. **Destroy!**

**Models 9100 & 9101 T-Shield Problem #1:** Affects model 9100 only made 4/85-8/85. Shield may break during use; **Problem #2:** made pre-1987. Strap may be missing button to keep straps from retracting too far; **Problem #3:** made 1/1/85-9/1/90. Button may be missing/work loose & present choking hazard; **Problem #4:** made 5/1/87-10/31/89. Shield may be hard to latch due to internal cracks. **Problem #5:** made 1985-1/26/89. White foam pad between pad & shell failed flammability tests. **Problem #6:** made pre-7/89. Metallic label glued to shield comes loose creating choking hazard. OR **Problem #7:** made 2/5/90-3/24/90. Possible structural weakness in metal tongue. **Problem #8:** made 2/8/91-1/24/92. Harness straps come unfastened at seat back. **Problems 1-8: Destroy!**

**Deluxe Tray Shield** Model 9104 made 6/15/92-9/4/92. **Problem:** Red button on buckle pops up preventing latching. **Destroy!**

## Ford (see Love Seat)

## Freedom Ride

(Out of Business) (No Recalls)

## General Motors

### Built-In Child Seats

**Integrated seats in Chevrolet Oldsmobile & Pontiac vans w/ power sliding doors** made 11/92-7/93 & 9/93-3/94. **Problem:** Needs new trim panel so belt doesn't catch in door. **Call:** dealer.

**Chevrolet & GMC ML Integrated Seats in vans** made 5/96-9/97. **Problem:** Harness may be missing hidden piece & will not lock! **Call:** dealer for inspection & replacement.

### Gerry (see Evenflo)

## Graco

800-345-4109 [www.gracobaby.com](http://www.gracobaby.com)

### Infant Seats

**580 Problem #1:** models 4580, 4581, 4583, 4585 made pre-12/31/89 (8912 & lower). When adjusting or relocating straps, parents may improperly rethread through metal retention slides. In sudden stop/crash, straps will not restrain child. **Destroy!** **Problem #2:** models 4581, 4583, & 4585 made pre-11/89 (8910 & lower). Retaining screws on handle may loosen & separate from seat. **Destroy!**

**Century Infant Seats & 4-in-1 Systems with straight handles** (W-shaped handles not affected). Seats made 1/01/91-7/31/97. **Problem:** Handle releases unexpectedly when carried causing seat to flip & unbuckled child to fall. **Destroy!**

**All Century Infant Seats & 4-in-1 Systems.** All models beginning "45" or "11" **Problem:** ???? made 9/12/95-5/13/96 (091295-051396) & having date code 255-95 through 365-95 or 001-96 through 131-96 on buckle top (above red push button on either side of the word "Infant") are affected. **Destroy!**

**SnugRide Problem #1:** Models 8402, 8402L03, 840301, 840303, 840302, 8402L03, 8412, 8442, 8442GMP, 8442L, 8442LBLW, 8442LCYP, 8442LMAD, 8443, 8443L, 8444, 8444L, 8444LHAB, 8444LHIG, 8446, 8446L, 8446LFBK, 8446LVIN, 8464MAC, 8464MEL, 8447, 8447L, 8447LHAV, 8448, 8448L, 8457, 8458, 8459, 8601, 8463, 8463AMB, 8463GMP, 8463JUN, 8463YL, 8464, 8470, 8471, 8478, 8602AMB, 8602JUN, 8602MAN, 8603MIC 8603MLL, 8605HIG, 8605KER, 8605PLT, 8607LAG, 8607NGS, 8608DIA, 8609FOF & C844342 made 3/1/02-3/8/03. Hardware may be missing to attach carrier to base. If missing

carrier may not securely attach causing injury in crash. **Destroy!** **Problem #2:** models 7493G9, 7493RS, 7497HL, 7497SY, 7499LK, 7499N2, 841101, 841102, 841103, 841203, 8412T02, 8457D5, 8457DVB, 8457F3, 8457GP, 8457IND, 8457MA, 8457MV, 8457RG, 8457TMJ, 8457TMP, 8457YL, 8458A5, 8458AE, 8458B7, 8458D8, 8458FKB, 8458HE 8458HH, 8458KY, 8458N5, 8459VL, 8460LV, 8462HAV, 8462JAM, 8471UVB, 8472BLW, 8472BRN, 8472CYP, 8472GMP, 8472MAD, 8472YL, 8474HAB, 8474MEL, 8476VIN, 8477HAV, 8477JAM, 8477NGS, & 8478SAR made 8/31/99-2/28/02. Seat may be missing metal hooks or "U" bars attaching carrier to base. If missing, carrier may not securely attach causing injury in crash. **Destroy!**

**SnugRide Problem #1:** Models 8609, 8616, 8643, 8645 & 8646 made 8/1/06-6/30/07. On some seats, backing on seat pad may pull away from seams allowing child to reach filling & creating choking hazard. **Call:** 800-345-4109 for replacement seat pad. **Problem #2:** Models C844342 & 794202, & these models beginning with "84": 02, 02L03, 0301, 0303, 0302, 02L03, 12, 42, 42 GMP, 42L, 42LBLW, 42LCYP, 42LMAD, 43, 43L, 44, 44L, 44LHAB, 44LHIG, 46, 46L, 46LFBK, 46LVIN, 64MAC, 64MEL, 47, 47L, 47LHAV, 48, 48L, 57, 58, 59, 63, 63AMB, 63GMP, 63JUN, 63YL, 8464, 70, 71, 78, & models beginning with "86": 01, 02AMB, 02JUN, 02MAN, 03MIC 03MLL, 05HIG, 05KER, 05PLT, 07LAG, 07NGS, 08DIA, 09FOF & made 3/1/02-3/8/03. **Problem:** Hardware may be missing to attach carrier to base. If missing carrier may not securely attach causing injury in crash. **Destroy!**

### Convertible Seats

**Models 1000, 2000, 3000 & 5000 STE** made 12/90-10/91 (9012-9110). **Problem:** Spanish labels have "bebes" & "ninos" transposed at belt path. **Destroy!**

**2000 STE T-Shield Problem #1:** made pre-6/89, (8906 & lower). Shoulder straps may be glued (not sewn). Check loops at splitter plate on seat back. **Destroy!** **Problem #2:** models 4253, 4261, 4263, 4265 & 4266 made 12/91-4/30/92, (9112-9204). Push button can fail allowing shield/harness to release. **Destroy!**

**3000 STE Tray-Shield Problem #1:** Fabric on shield has Velcro, child may unfasten Velcro & pull apart foam. **Problem #2:** models 4365 & 4368 made 5/7/90-6/14/90 (9005-9006). Latch tongue breaks in crash allowing child to slip out. **Problem**

**#3:** models 4353, 4365, & 4368 pre-1/1/91 (9101 & lower). Instructions may not advise when to switch from rear to forward latching positions. Failure to switch to forward latching position for a child more than 30 lbs. makes release difficult after crash. **OR Problem #4:** made 9/89-4/92 (8909-9204) release button rotates up in crash making release difficult. Note: Some seats were repaired with defective button. **Problems 1-4: Destroy!**

**3500 STE Tray-Shield** made 9/89-4/92 (8909-9204). **Problem:** Release button rotates up in crash making release difficult. Note: Some seats were repaired with defective button. **Destroy!**

**5000 STE Tray-Shield Problem #1:** models 4450, 4460, 4470, & 4475 pre-1/1/91 (9101 & lower). Instructions may not advise when to switch from rear to forward latching positions. Failure to switch to forward latching position for child more than 30 lbs. makes release difficult after crash. **Problem #2:** Seats made 9/89-4/92 (8909-9204). Release button rotates up in crash making release difficult. Note: some seats were repaired with defective button. **Problem #3:** models 4470 & 4475 made 5/90-6/90 (9005-9006). Latch tongue breaks in crash allowing injury. **Problems 1-3: Destroy!**

**5500 STE** made 9/89-4/92 (8909-9204). **Problem:** Release button rotates up in crash making release difficult. Note: some seats were repaired with defective button. **Destroy!**

**Model 4100 & 4200 Problem #1:** made 4/85-2/86 (8504-8602) w/ "mold #1" engraved above top bar. Plastic too thin under child's bottom. **OR Problem #2:** made 1/81-4/81 (8101-8104). Buttons on pad loosen & present choking hazard. **Problem #3:** made 1/1/81-1/1/83 (8101-8212). Buckle release is difficult. **Problem #4:** model 4200 made 6/81 has wrong washers. **Problems 1-4: Destroy!**

**Model 4300** made 4/85-2/86 (8504-8602) w/ "mold #1" engraved above top bar. **Problem:** Plastic too thin under child's bottom. **Destroy!**

**Model 4400XL Problem #1:** Made 4/85-2/86 (8504-8602) w/ "mold #1" engraved above top bar. Plastic too thin under child's bottom. **Destroy!** **Problem #2:** Made pre-5/86, (8604 & lower). New label needed to tell if restraint is properly locked. **Destroy!**

**Accel** models 45100CHT, 45100MTE, 45100STH, 45200MXM, 45600JTI, 45600MTE, 45600MTO, 45600MXM, 45600SAF, 45700GSD, & 45700LFT made 4/9/01-5/10/01.

**Problem:** When used forward-facing, harness adjuster allows webbing to slip. Child may not be properly restrained. **Destroy!**

**Bravo** models 44622LTC, 44630LTH, 44631PFN, & 44662WSC made 4/9/01-5/10/01. **Problem:** When used forward-facing harness adjuster allows webbing to slip. Child may not be properly restrained. **Destroy!**

**ComfortSport.** **Problem #1:** Some harness buckles can become more difficult to open or become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. Order replacement buckle using Graco's online order form at [GracoBuckleRecall.com](http://GracoBuckleRecall.com) or call: 877-766-7470. **Problem #2:** models 8C04FRR & 8C04FRR2 made 11/1/2006-10/08/2007. Seat has large "body pillow" that partially covers airbag warning label. **Call:** 800-345-4109 Graco will instruct consumer to discard body pillow which is for comfort only & does not affect safety of seat. **Problem #3:** Models 8629TDL, 8630MTR, 8631DFT, 8631DRA, 8632PSO, 8635TAC, 8639COS, 8C00BLG, 8C00DMN, 8C00GRP, 8C00LNW, 8C00MID, 8C00TMB, 8C01SVD, 8C01WTN, 8C02MGI, 8C02MRC, 8C03HAL, 8C03WCF, 8C04FRR, & 8433FOF. Made 1/2/07-7/31/07. Some seats may have Lower Anchor belt misrouted causing seat to exceed safe angle in crash. Do NOT use LATCH to install seat rear-facing until repaired! Instead use seat belt. **Call:** 800-345-4109 for instructions.

**Encore** models 44612GTN & 4662WSC01 made 4/9/01-5/10/01. **Problem:** When used forward-facing harness adjuster allows webbing to slip. Child may not be properly restrained. **Destroy!**

**SmartMove** Models 44709MTE & 44709SVR made 4/9/01-5/10/01. **Problem:** When used forward-facing harness adjustment mechanism allows webbing to slip. Child may not be properly restrained. **Destroy!**

**Smart Move Tray Shield** model 4750 made 12/5/95-2/13/96 (120595-021396). Affected seats, have number: WO#-138442-01, WO#-136716-01, -02, or -03 on white label sewn to harness near splitter plate. **Problem:** Latch can release when seat is forward-facing & harness in slot closest to crotch. **Destroy!**

**Triumph Problem #1:** model 264 made 10/20/01-1/31/02. The slide loop connectors holding harness may not be strong enough to properly restrain child. **Call:** 800-233-5921 for upgrade kit. **Problem #2:** model 264, 359, & 389 made 9/6/01-10/31/05. Child may pull back cloth



cover accessing foam liner becoming choking hazard. **Call:** 800-490-7591 for protective sleeve.

### **Combination Seats**

**Breverra Premiere & Br ????????**

**CarGo, Platinum CarGo, Treasured CarGo, & Ultra CarGo** models 8487BELI, 8487SMP, 8487WBR, 8686ROS, 8689FAR, 8D01ZPH, 8D02SYC, 8D03WIK, 8D04SDN, 8D05NWY, & 8D10CCE made 1/9/2007-3/3/2008. **Problem:** NHTSA Hotline phone number on label affixed to seat back may be incorrect. Should read 888-327-4236. **Call:** 800-345-4109 for sticker kit.

### **Booster Seats**

**Breverra Premiere & Breverra Contour** all models w/ harness made 2/1/95-7/10/98. **Problem:** Buckle can crack or break. **Destroy!**

### **International (Out of Business)**

**Astroseat** made pre-8/81. **Problem:** Buckle pulls through webbing. **Destroy!**

### **Kantwet (see Evenflo)**

**Kolcraft (No longer makes car seats)** 1100W Monroe Street, Chicago, IL 60607, 800-453-7673, [www.kolcraft.com](http://www.kolcraft.com)

### **Infant Seats**

**Infant Rider, Travel-About, Plus 4, Plus 5, & Carters Travel 5.** Look for 5-digit model # beginning 131xx, 138xx, or 368xx made 3/4/96-9/30/96. **Destroy!**

**Infant Restraint, Infant Car Seat, Infant Rider, Secura, Travel-About, Plus 4, Plus 5, & Playskool** (some w/ strollers) models 1312x, 1382x, 1383x, 1384x, 1385x, 368xx, 43xxx, & 7700x made 1/1/93-6/30/99. **Problem:** Handle moves unexpectedly causing seat to rotate; allowing unbuckled child to fall. **Destroy!**

**Rock 'N Ride** model 13123 **Problem #1:** made 1/85-6/85. Plastic may crack in crash. **Destroy!** **Problem #2:** made pre-4/90. Plastic clips attaching pad present choking hazard. **Destroy!**

### **Convertible Seats**

**Automate T-Shield Problem:** model 180-600 & 180-601 made 1/30/92-3/22/93. Crotch buckle rusts. **Destroy!**

**Dial-A-Fit Problem #1:** made 10/1/88-8/16/89. Too much forward head movement in crash. **OR #2:** made pre-4/90. Buttons attaching

pad break & present choking hazard. **Problems 1-2: Destroy!** **Dial-A-Fit II** model 180-600 made 11/1/90-6/30/91. **Problem:** In rear-facing tests shell cracked. **Destroy!**

**Perfect Fitt** model 180-200 made pre-10/90. **Problem #1:** Failed flammability test. **Problem #2:** models 180-150 & 180-200 made 3/1/89-10/1/90. Too much forward movement in crash increases risk of injury. **Problem #3:** made pre-4/1/90. White pad clips break presenting choking hazard.

**Problems 1-3: Destroy!** **Performa Tray-Shield Problem #1:** made 3/96-5/31/96. Flammable cover. **Destroy!** **Problem #2:** made 1/26/96-7/31/97. Buckle release difficult after crash. **Destroy!**

**Playskool Problem #1:** models 140-155 & 180-400 made 12/89-8/90. Flammable foam pad. **Destroy!** **Problem #2:** models 77001 & 77002 w/ comfort pump made 1/1/91-6/30/93. Label missing & crotch buckle rusts. **Destroy!**

**Secure-Fit** made 1/26/96-7/31/97. **Problem:** Buckle release difficult after crash. **Destroy!**

**Traveler 700 Problem #1:** made after 11/1/94. Buckle performance questionable. **Problem #2:** model 150-100, Style 13400 & 13401 made 1/1/91-8/7/91. Shield may break. **Problem #3:** Dates unknown. Labels have incorrect drawings. **Problem #4:** made 1/24/91-6/30/93. Crotch buckle rusts. **Problems 1-4: Destroy!**

### **Booster Seats**

**Flip 'N Go** Model 191-100 & 191-200 style 19127 made pre-3/19/87. **Problem:** Defect in shape of shield. **Destroy!**

### **LillyGold**

800-829-1625 [www.lillygold.com](http://www.lillygold.com)

### **Convertible Seats**

**Sit 'n' Stroll Problem #1:** Model 4002 made 5/5/08. Harness adjuster webbing fails to meet strength requirements, may cause child to be improperly restrained in a crash. **Call:** 800-829-1625 for repair kit with replacement harness adjuster strap. **Problem #2:** Model 2003 made 9/1/02-10/21/03. Too much forward head movement when used with lower seat belt path or shoulder & buckle pads. Also pads may interfere w/ ability to tighten harness. Remove/discard shoulder & buckle pads & use only upper forward-facing belt path. **Destroy!**

### **Lin Lih Counterfeit Seat**

**Problem:** Import seat failed

government crash test! If you see this seat for sale, or have purchased one, DO NOT USE! **Call:** 800-424-9393.

### **Little Cargo**

(Out of Business) (No Recalls)

### **Love Seats (Out of Business)**

#### **Infant Seats**

Models 4477B1-4477M1 & 4477A2-4477F2. Made 1/81-7/82. **Problem:** Defective plastic. **Destroy!**

#### **Forward Facing Only Seats**

**All non-adjustable Toddler seats** made 3/84-11/20/84, Lot 4477C4 (stamped on rear). **Problem:** Defective plastic. **Destroy!**

### **Mercedes Benz USA**

(Child Seats manufactured by Britax)

#### **Infant Seats**

**Infant Seats & Boosters** made 2/97-7/99. **Problem:** Baby Smart air bag deactivation device fails to turn off passenger air bag. **Call:** Dealer for replacement.

#### **Forward Facing Only Seats**

**Top Safe Child Seat** made 3/1/03-11/30/03. **Problem:** Lower LATCH attachment may detach in crash causing injury. **Call:** Dealer for refund recall campaign #2004 120005. Use seat belt to secure seat.

#### **Booster Seats**

**Booster Seats** made 2/97-7/99. **Problem:** Baby Smart air bag deactivation device fails to turn off passenger air bag. **Call:** Dealer for replacement.

### **Mia Moda, Inc./Larado**

866-642-6632  
[www.miamodainc.com](http://www.miamodainc.com)

#### **Infant Seats**

**Mia Moda Viva** Model 5000 & 5001 made 12/19/06-2/6/07. **Problem:** Lower LATCH attachment may interfere with connection of carrier/base after tightening anchors. May still hear audible click indicating secure connection. Pulling up on carrier handle may also indicate secure connection. In severe crash carrier may detach causing injury. Also, required registration card was not provided w/ seats or separate bases. Note: Until repaired install using vehicle seat belt. **Call:** 866-642-6632 for lower anchor assembly & serial number labels.

### **Orbit Baby**

877-672-2229, [www.orbitbaby.com](http://www.orbitbaby.com)

#### **Infant Seat**

**Orbit Baby Car Seat Bases** **Problem #1:** G2 Bases Model Number: ORB822000 with Batch #A0840, A0860 or A0880 made 3/20/13 - 7/20/13. StrongArm knob may detach or spin without tightening base preventing proper installation. First register seat at Orbit's website, then **call:** 877-672-2220 for StrongArm knob repair kit. If seat is not tightly secured then install seat without base until repaired. **Problem #2: All Orbit Baby Bases** made pre-2/2008. Base must be upgraded for use w/ Toddler Car Seat. **Call:** 877-ORB-BABY or visit [www.orbitbaby.com](http://www.orbitbaby.com). To receive new base w/ green circular seal, Toddler seat & Base must both be registered.

### **Peg-Pérego**

3625 Independence Dr, Fort Wayne, IN 46808, 800-671-1701, [www.pegperego.com](http://www.pegperego.com)

#### **Infant Seats**

**All Primo Viaggio Seats/Travel Systems Problem #1:** Seats w/ dark button in red circle made 5/20/01-2/15/02. Snap & fabric interfere w/ harness preventing seat from latching. **Destroy!** **Problem #2:** made 2/1/01-6/10/01. Left latch may not lock seat into base causing injury/death in crash. **Destroy!**

**Primo Viaggio SIP 30/30** Models beginning "IMUN00US" 32MD41KN41, 35CR13BU13, 35CR13PL46, 35CR24BU24, 5TL49KN53, 35TL53KN46, 61ST13IC53, 61ST34IC53, & 61ST48IC53 made 7/1/07-3/14/08. **Problem:** plastic harness adjuster cover may have sharp edge that can cause cuts or scratches to bare legged infants. 888-734-6030 for new adjuster cover.

### **Playschool (see Kolcraft)**

### **Porsche (Seats made by Britax)**

**Porsche Child Seat for '97-'98 Boxters, 911 Carrera, Carrera S, 911 Carrera 4, 4S & 911 Turbo.** **Problem:** Air bag deactivation may not work. Air bag may deploy. **Call:** Dealer, do not use until repaired.

### **Pride Trimble (see Evenflo)**

#### **Convertible Seats**

**Model 832** made 1/88-4/89. **Problem:** Using optional armrest, head moves too far forward in

crash. **Destroy!**

### **Booster Seats**

**Click 'n Go** model 890, 891 & 892 made 2/86-10/87. **Problem:** Failed testing. **Destroy!**

### **Questor (See Evenflo)**

### **Recaro**

888-973-2276 [www.recaro.com](http://www.recaro.com)

**Como** All models made pre-12/18/07. **Problem: #1** Harness can disconnect from harness connector (splitter plate) as child is taken in/out of seat. In crash, unsecured child can be injured. **Call:** 800-873-2276 for rubber caps to close gap allowing harness to disconnect. **Problem #2:** All models made pre-9/17/07. Forward-facing shoulder belt guide (previously called lock-off) may not prevent some older style (ELR) seat belts from loosening. **Call:** 800-873-2276 for locking clip in this consumer advisory campaign.

**Signo Problem:** All models made pre-12/18/07. Harness can disconnect from harness connector (splitter plate) as child is taken in/out of seat. In crash, unsecured child can be injured. **Call:** 800-873-2276 for rubber caps to close gap allowing harness to disconnect.

### **Renolux (Out of Business)**

#### **Convertible Seats**

**GT-1000** #69985, made 1/85-1/86. **Problem:** Rear-facing failed test. **Destroy!**

**GT-2000 Problem #1:** made 1/1/92-1/31/93, foam compresses too much. **Problem #2:** made 5/89-6/9/93, failed flammability test. **Problem #3:** made 8/15/88-10/31/88 (also labeled **Champion Children's Products GT-1000** or **F.B.S.** model 200). Buckle releases too easily & seat is too reclined when rear-facing. **Problems 1-3: Destroy!**

**GT-4000 Problem #1:** made 1/1/92-1/31/93, foam compresses too much in crash. **Destroy! Problem #2:** made 5/89-6/9/93 failed flammability test. **Destroy!**

**GT-5000 and Turn-A-Tot** model 500 **Problem #1:** made 2/18/90-4/29/91 base allows too much forward movement in crash; failed flammability test. **Problem #2:** made 1/1/92-1/31/93, foam compresses absorbing crash impact; base allows too much forward movement in crash; failed flammability test. OR **Problem #3:** made 5/89-6/9/93 failed flammability test. **Problems 1-3: Destroy!**

**GT-5500 Problem #1:** made 1/1/92-1/31/93, foam compresses too much in crash. **Destroy! Problem #2:** made 5/89-6/9/93, fail flammability test. **Destroy!**

**GT-7000** all models. **Problem #1:** made 1/1/92-1/31/93 foam compresses too much in crash. **Problem #2:** Remote attachment can overheat & smoke increasing risk of fire. **Problem #3:** made 5/89-6/9/93, fail flammability test. **Problems 1-3: Destroy!**

### **Snug Seat**

800-336-7684, [www.snugseat.com](http://www.snugseat.com)

#### **Special Needs**

**Gorilla Models 200-1000** made 6/26/02-1/15/03. **Problem:** Washer on tether may rust. In crash, tether may break causing injury. **Destroy!**

**Spelcast Models 600-1000** made 6/26/02-1/15/03. **Problem:** Washer on tether may rust. In crash, tether may break causing injury. **Destroy!**

### **Strolee (Out of Business)**

#### **Convertible Seats**

**Wee Care 599** made 12/15/80-5/29/81. **Problem:** Clips on armrest present choking hazard. **Destroy!**

**Models 609 & 610 Problem:** Plastic may crack. **Destroy!**

**GT-3000** made 1987-88. **Problem:** Seat failed crash test rear-facing. **Destroy!**

#### **Booster Seats**

**Quick-Click 605** w/ 4/85 stamped on seat bottom. **Problem:** Failed crash test. **Destroy!**

### **Team-Tex & Car Seat**

**Specialty** 877-912-1313

#### **Infant Seat**

**Baby Ride Problem #1:** Model 374199 made 12/18/08. Belt routing label w/ horizontal reference line is misplaced. May cause seat to be overly reclined. **Call:** 877-912-1313 for label & placement instructions

### **Triple Play Products**

904 Main St, Ste. 330, Hopkins, MN, 55343, 800-829-1625  
[www.tripleplayproducts.com](http://www.tripleplayproducts.com)

#### **Convertible Seats**

**Sit 'n' Stroll Problem #1:** model 3240 made 6/9/97-8/9/97. Missing air bag warning label. OR **Problem #2:** model 3240 made 11/1/96-6/30/99. Incorrect rear-facing weight limit on label. Use seat rear-facing only up to 22 lbs. OR **Problem #3:** model 3240 made 11/1/96-6/30/99.

Incorrect rear-facing weight limit on label. Use seat rear-facing only up to 22 lbs. OR **Problem #4:** model 2240 made 4/01-10/01. Certification label printed in yellow instead of red. **Problems 1-4 : Destroy!**

**Tomy International** 800-704-8697 [www.tomy.com](http://www.tomy.com)

#### **Infant Seat**

**Learning Curve** models 1420 (with fabric codes ARD, FUI and MAR) made 5/7/06 - 5/15/06. **Problem:** Shell may crack in crash if metal slide on end of crotch strap is not installed correctly. Assure metal slides lie flat against shell in correct location. **Call:** 800-704-8697 for assistance.

### **Triple Play Products**

10275 Wayzata Blvd, Suite 280, Minnetonka, MN 55305, 800-829-1625  
[www.tripleplayproducts.com](http://www.tripleplayproducts.com)

#### **Convertible Seats**

#### **Sit 'n' Stroll**

- Problem #1:** Model 2003 made 9/1/02-10/21/03. When used w/ lower seat belt path and/or shoulder & buckle pads are used, seat permits too much forward head movement. **Destroy!**
- Problem #2:** model 2240 made 4/01-10/01. Certification label printed in yellow instead of red. **Destroy! Sit 'n Stroll**
- Problem #3:** Model 4002 made 5/5/2008. Harness webbing failed crash testing increasing risk of injury to child. **Call:** 800-829-1625 for repair kit.

### **T.R.W. (See Love Seat)**

### **Virco (See Pride Trimble)**

### **Volvo Cars North America**

Seven Volvo Drive  
Rockleigh, NJ 07647, 800-458-1552,  
[www.volvocars.com](http://www.volvocars.com)

**All child seats! Problem:** Child can open buckle too easily. **Call:** Dealer to arrange for return of seat.

### **XSCi (Out of Business)**

**All Infant Seats** made 2/1/02-3/7/02. **Problem:** In crash, child's head moves too far forward & cradle may detach causing injury or death. **Do not use! Destroy!**