



Car Seat Recalls/Defects and Safety Notices - Revised 5/3/2018

Open your smart phone camera; focus over the QR Code (left) and follow the popup link to ensure you have the most recent version covering child car seats manufactured after 12/31/08. The list is a publication of the Washington State Safety Restraint Coalition 1-800BUCKLUP (800 282-5587) www.800BUCKLUP.org). Information may change. Always call manufacturer to verify. For older seats see separate Archive List (revised yearly). The most recent addition(s) are shaded.

4moms

888-614-6667 www.4moms.com

Infant Seat

Self-installing Car Seat made 7/1/16 - 10/31/16. **Problem:** Hooks locking carrier to base may stick or fail to attach. Until replaced, double check proper locking into base by pulling up on carrier handle; or install carrier without base. **Call 888-614-6667 or visit www.4moms.com/recalls or call:**

Aidia, Inc.

(No Recalls)

866-328-8661 www.aidiaproducts.com

Angel Guard

(No Recalls)

800-815-6330 www.angel-guard.com

Aprica

(No Recalls)

888-569-7288 www.urbinibaby.com

Aria Child

(No Recalls)

888-569-7288

Baby Jogger, LLC

800-241-1848 www.babyjogger.com

Infant Seats

- **City GO Infant Seat** Models BJ64510, BJ64529;
- **City GO Infant Car Seat Base** Models BJ80400, BJ61500;
- **City Mini Car Seat Stroller System** Model BJ72510;
- **Vue Lite Car Seat Stroller System** BJ70411, BJ70424, BJ70431

Made 11/3/14 - 4/30/15. **Problem:** Incorrect/missing information on labels/instruction book may decrease correct use of seat increasing risk of injury. **Call:** 800-241-1848 for free replacement.

Baby Trend

800-328-7363 www.babytrend.com

Combination Seat

3-in-One Hybrid LX model FB48417 made 7/14/16 sold only at Wal-Mart & model FB58181 made 7/23/16 sold only at Military Exchanges. **Problem:** In a crash, center adjuster may detach in harnessed mode if child weighs more than 40 pounds. To learn if your seat requires free replacement **go online www.babytrend.com or**

call: 800-328-7363

3-in-One TrendZ Fastback Models FB60070, FB60408 made 10/11 - 7/13.

Problem: Buckle may become difficult to unlatch or become stuck in latched position. **Call:** 800-328-7363 for new buckle. Effectiveness of buckle to restrain child is NOT affected.

Bergeron

(No Recalls)

800-371-2778 www.adaptivemall.com

Britax

888-427-4829 www.britaxusa.com

Infant Seats

B-Safe 35 Models

- Beginning E1A: 183F, 185M, 185P, 186R, 203F, 205M, 205P, 206X, 206Z, 207E
- Beginning E9LU: 65V, 66X, 66Z, 67D, 67E. EXA185M
- Beginning S020: 63600, 63700.
- Beginning S03803: 400, 500, 700, 800, 900
- Beginning S04: 144400, 144500, 144600, 145000, 402800, 884200, 884300, 975600, 978900
- Beginning S0: 5260200, 6020300, 6020400, 6020500, 6020600, 6020700, 6020800, 6020900, 6147100
- S921800

B-Safe 35 Elite Models

- Beginning E1A2: 15T, 15U, 16P, 21Q, 25C, 25U, 26L
- Beginning E9L: S5: 1Q, 6C, 6L, 7F, 7G, 7H
- EXA216L
- Beginning S0: 1298600, 2063800, 2063900, 2064000, 4281200, 4281300, 4628500, 6018800, 6020000, 6020200
- S923700

BOB B-Safe 35 Models E9LT34A, E9LT34C, E9LT35X, EXLT34A. All made 11/1/15-5/31/17.

Problem #1 of 2: Center tab on chest clip can break presenting choking hazard to infant. **Order remedy kit at bsafe35clip.com or call:** 1-833-474-7016

Problem #2: B-Safe 35 Models made 10/1/14 - 7/1/15.

- EXLU65M and those
- Beginning E9L: U65M, U65P, U63F, U66R, S63F.

B-Safe 35 Elite Models Beginning E9LS: 55T, 56P, 55U, 66C, 65U and

B-Safe Travel System Models

- beginning "S91: 4900, 5400, 5200
- S921900
- S01635200

Problem: Car seat carry handle may crack/fracture while carrying it, causing risk of injury to child. Do not carry by handle until fixed. Recall does not affect seat when used in vehicle or on stroller. Watch video bsafe35recall.com & order remedy kit; or **Call:** 800-683-2045

Chaperone Problem #1: Models beginning "E9L692" J, K, L, & M made 9/1/10 - 4/30/11. Harness adjuster may detach from the shell. Should it detach, harness straps will not properly secure child/increasing risk of injury in a crash. IF harness adjuster on your Chaperone Infant Car Seat detaches, discontinue use of the product immediately and contact Britax. **Call:** 888-427-4829 for remedy kit.

Problem #2: Models begin "E9L69" N9, P2, P3, & P5 made 4/09 - 5/10. Chest clip is brittle & may break causing sharp edges/choking hazard. **Call:** 888-427-4829 for new chest clip. If clip breaks remove it. May continue to use seat until replacement chest clip is installed.

Convertible Seats

Advocate 70-G3, Boulevard 70-G3 and Pavilion 70-G3

models begin "E9L" J91A, E91M, J91S, J92E, J93P, J93S, K91A, K31A, K31Q, K32D, K32Z, K33Q, L11A, L11Q, L12D, L12Z, G81A, G83N, G83P, G83X, G83Y, L21A, L23P, L23Y made 6/1/12 - 8/31/12.

Problem: Child chewing on HUGS chest pad may bite off small piece, presenting choking hazard. **Call:** 888-427-4829 for new HUGS chest pads. New HUGS pads are marked "PP" under harness webbing.

Advocate ClickTight Models E9LT86F, E1A135Q, E9LT86G, E9LT85Q, E9LT86A, E9LT86H, E9LT85S, E1A015Q, E1A016A, and E1A016H made 8/1/14 - 7/29/15.

Problem: Red harness adjuster button may remain in release position preventing harness from locking. Continue using seat if harness button does not stick & harness remains tensioned. **Order www.BritaxClickTightConvertibleRecall.com or call:** 1-888-427-4829, Option 3.

Boulevard ClickTight models beginning "E1A" 013Q, 016A, 016H, 135Q, LT85Q, or beginning "E9LT" 85Q, 85S, 86A, 86F, 86G, 86H made 8/1/14 - 7/29/15. **Problem:**

Harness adjuster button (red) may remain down in release position and prevent harness from locking. Continue using seat if harness button does not stick and harness remains tensioned. All registered owners will receive a repair kit automatically. **Order at BritaxClickTightConvertibleRecall.com or call:** 1-888-427-4829, Option 3.

Marathon ClickTight models E1A116L, E9LT76P, E9LT71Q, E9LT76N, E9LT76B, E9LT75R, E9LT76L, E1A006B, E1A005R and EXA116L made 8/1/14 - 7/29/15. **Problem:** Red harness adjuster button may remain down in release position preventing harness from locking. Continue using seat if harness button does not stick and harness remains tensioned. **Order at BritaxClickTightConvertibleRecall.com or call:** 1-888-427-4829, Option 3.

BubbleBum

(No Recalls)

800-969-6586 www.bubblebum.co/us

CARES

(No Recalls)

800-299-6249 www.kidsflysafe.com

Chicco

(No Recalls)

877-424-4226 www.chiccousa.com

CLEK Inc.

(No Recalls)

866-656-2462 <http://clekinc.com>

Columbia Medical

(No Recalls)

800-454-6612 www.columbiamedical.com

Combi USA, Inc.

800-992-6624

www.combiusa.com

Convertible Seats

Coccoro Model 8220 made 1/1/09-7/31/16.

• **Problem 1 of 2:** When installed forward-facing & secured with vehicle LAP-ONLY belt, excessive force may be transferred to car seat occupant in a crash increasing risk of injury. (Recall does not affect use of seat when installed rear-facing. If installed forward-facing with lap/ shoulder belt & lock-off or lower anchors and tether). **Order** Remedy Kit online at <http://registration.combiusa.com/re> call or call: 888-232-3294.



• **Problem #2: Coccoro** Model 818220 made 1/1/09 - 12/31/12
Zeus Turn Model 8815 made 7/15/07 - 3/31/09

Zeus 360 made 2/1/09 - 5/31/12.
Problem: Embedded plastic button prevents harness from meeting minimum breaking strength when tested independently from child restraint. Could affect overall performance of child restraint in the event of crash. To register and get new straps **Call:** 844-697-1690 or [Safety-Notifications/Recall-Information](#) Combi encourages use of seat until kit is received and installed.

.....
Compass (See Tomy)

.....
Convaid
(No Recalls)
888-266-8243 [convaid.com](#)

.....
Cosco (See Dorel)

.....
Cybox 800-593-5522
[cyboxonline.com](#)

Booster Seats

Cybox Solution X-fix Models 0500200 & 0500760 made 2/1/10 - 2/28/10. **Problem:** Seats are labeled with incorrect warning related to securing an unoccupied booster. Increases risk of unoccupied booster striking vehicle occupants causing injury in a severe crash. Go to [www.regallager.com/recall](#) or **Call:** 800-593-5522 for a new warning label and Owner's Manual. Safety of the seat when used with a properly secured child is not affected. If the seat is unoccupied, ensure it is belted into the vehicle with the vehicle seat belt even when using the LATCH connectors.

.....
Diono 855-463-4666 [diono.com](#)

Convertible Seats

Radian RXT, Radian R100, Radian R120, Rainier, Olympia, & Pacifica convertible seats made 11/25/2013 - 9/25/2017. **Problem:** The seat may not adequately protect a child *when used in harnessed mode & installed forward-facing*. Children using seat in booster mode are not affected. Forward-facing children using the harness, who weigh more than 65 pounds (with any installation method) **MUST** use top tether. For vehicles not equipped with tether anchor use seat in booster mode.
For forward-facing children using the

harness who weigh 65 pounds or less, whose seat is installed with a lap-only belt in vehicles not equipped with a tether anchor **MUST** install the free repair kit (energy absorbing pad & chest clip). **Call:** 855-215-4951 or visit <https://us.diono.com/safety-notice/>

Dorel Juvenile Group

(Cosco, Eddie Bauer, Safety 1st, Maxi Cosi, Quinny)
800-544-1108 [djgusa.com](#)

Infant Seats

All Infant Seats sold as part of a stroller system under Safety 1st, Cosco, Disney, or Eddie Bauer Made 1/6/08 - 4/6/09. Models, beginning "22-" were sold under the following names and numbers:

- **Safety 1st Sojourn:** 057 DBY, 085 DWA, 057 CLN, 057 HRT, 322 HRR, 322 PTK, 057 LPH, & 085 LYN.
- **Safety 1st Eurostar:** 322 KDL, 322 LXI, 322 OLY, 322 PRS, 322 MAI, & 325 COB.
- **Safety 1st Explorer:** 095 RBK.
- **Safety 1st Lite Wave:** 380 LGA & 380 MSA.
- **Safety 1st Vector:** 627 WAV & 325 PAC.
- **Cosco Sprint:** 300 FZN, 300 OSF, 300 CSF, 300 JIV, 300 THD, & 300 TWD.
- **Disney Propack:** 627 AWF, 355 LBF, 305 NAB, 305 PPH, & 355 PWK.
- **Eddie Bauer Adventurer:** 627 CGT, 627 FRK, 627 SNW & 627 WPR.
- **Eddie Bauer Endeavor:** 627 KGS & 655 BYTE.

Problem: Handle releases suddenly when carried. Seat may flip & child may fall. **Order** handle repair kit **online** <http://www.djgusa.com> or **Call:** 866-762-3316 or. Until installed, do not use handle to carry.

Comfy Carry Model IC123 FSM made 5/1/11 - 4/25/12. **Problem:** Some seats were sold without lower LATCH attachment strap. **Call:** 877-416-8111 for replacement base with LATCH. Until new base is received consumers should use the seat installed with a seat belt.

Maxi-Cosi Mico Models beginning "22-" 371CIP, 371CTR, 371FSB, 371LYP, 371MJR, 371PHT, 371RFR, 371TRL, & 372TTH made 5/1/08 - 4/30/09. **Problem:** Harness may gradually loosen during normal use increasing risk of injury in crash. Until repaired double check to assure harness is adjusted snugly around child. For repair kit **call:** 866-623-3139 or **email** <mailto:consumer@djgusa.com>

OnBoard Models beginning "22-" 077FSM, 078DMS, 346VAL, 356NTR,

356PRO, 356TRI, 657FRK, 657MTT, 657PST, 657SNW, 657SON, & 657VND also model IC-072SON made 5/1/08 - 4/30/09. **Problem:** Harness may gradually loosen during normal use increasing risk of injury in crash. Until repaired double check to assure harness is adjusted snugly around child. For repair kit **Call:** 866-623-3139 or **email** <mailto:consumer@djgusa.com>
OnBoard 35 Model IC124 FSM made 5/1/11 - 4/25/12. **Problem:** Some seats were sold without lower LATCH attachment strap. **Call:** 877-416-8111 for replacement base with LATCH. Until new base is received consumers should use the seat installed with a seat belt.

3-in-1 Seats

- **Safety1st Complete Air LX**
Models CC050AJH, CC050ANY, CC050ANZ, CC050AOQ
- **Safety1st Complete Air SE**
Models CC051AIR made 7/20/10 - 5/18/11. **Problem:** Arrows for rear-facing belt path installation may appear to point to forward-facing belt path. If not installed properly child may be injured in a crash. **Call:** 877-675-2355 for new label or **email** <mailto:rftbaselabel@djgusa.com>
- **Safety1st Alpha Omega Elite**
Models 22187ANL, 22187REM, 22187REMA, 22187SAR, 22187SARA, 22465FSM, CC033BMT, CC043ANK, CC043ANL, CC043AQS made 7/20/10 - 5/18/11. **Problem:** Arrows for rear-facing belt path installation may appear to point to forward-facing belt path. If not installed properly, child may be injured in a crash. **Call:** 877-675-2355 or **email** <mailto:rftbaselabel@djgusa.com> for new labels & instructions.

Alpha Omega, Alpha Omega Elite, Enspira, Maxi-Cosi Priori, Prospect, & Vantage Models begin "22-" made 5/1/08 - 4/30/09

- 148RDH, 149PAL, 150BNS, 152BVL, 152CMN, 152RGS, 154HTR
- Beginning 155: BDF, HMR, NSHE, OTC, TRP
- Beginning 158: BLL, GRS, SPA,
- 159SGT,
- Beginning 172: BKE, BRT, OKW, PHO, SVT,
- Beginning 77S: NP, SNP2
- Beginning 178: SCT, STL, VSS
- 185BVL2, 188BVL2, 195SVS, 195SVS2, 412
- Beginning 439: ABY3, HTP3, OKP3, VNS3
- 449GES, 452RBYE, 453BCT, 453FSM, 456BVL
- Beginning 456: CAB, CAO, CSR, LMT, MIL, MRR, NTM, NTR, PRO, SCY, SUZ, TRI, TTN
- 458FTM, 458NYC, 459MTG,

462BLN, 465BMT, 469BSE, 469BSEC, 475BVL,

Models

- Beginning 476: CIP, CTR, FSB, GIP, ISP, NOW, NRF, PHT, PMK, PNG,
- Beginning 486: CRI, GIP, TTH,
- 546BSE, 547CHA, 553BVL3, 554PCR, 554PCR3, 554RCR3, 561WAL
- Beginning 564: ARZ, MIL, NTR, OKW, PHO, PRO, TRI, VLC
- 567GRH, 574PCR3, 580BYR,
- 740HPN,
- Beginning 741: ATI, BWD, GRT, 741???,
- 755BLD
- Beginning 758: BYT, CMP, FRK, HDS, HID, KGS, PST, SNW, SON, VND
- 759MTT
- Beginning 790: CGT, SNW, WPR, WPR2,
- 799MER,
- Beginning 880: BYT, MTT, MTTA, SON, SONA
- 560FSM
- 93-560FSM, 17-439ABY, & 17-439HTP. **Problem:** Harness may gradually loosen during normal use increasing risk of injury in crash. Until repaired double check harness is adjusted snugly around child. For repair kit **call:** 866-623-3139 or **email** <mailto:consumer@djgusa.com>

Eddie Bauer Deluxe 3-in-1
Models beginning 22790CGT, CC046AAI, CC046AAU, CC046CTA, CC046SNW, CC046WPR made 7/20/10 - 5/18/11. **Problem:** Arrows for rear-facing belt path installation may appear to point to forward-facing belt path. If not installed properly, child may be injured in a crash. **Call:** 877-675-2355 or **email** rftbaselabel@djgusa.com for new labels & instructions.

.....
Downunder (No Recalls)

.....
Dream On Me (No Recalls)

732-748-1300 [dreamonme.com](#)

.....
Eddie Bauer (See Dorel)

.....
Evenflo 800-233-5921
[evenflo.com](#)

Infant Seats

- Embrace35** made 12/1/11 - 5/31/13. Models:
- 30711365,
 - Beginning 31511: 040, 323, 400, 398
 - 3151953, 31521138, 46811205, 46811237
 - Beginning 48111: 200, 215, 215A, 218, 234, 235, 235A, 11462,
 - Beginning 484: 11391, 11391D, 11392, 11504, 11504d
 - Beginning 52: 911307A, 921040,

- Beginning 55: 311138, 311238, 311292

Problem: Harness buckle may become stuck in latched position making it difficult to remove child. **Call:** 800-490-7591 for new buckle or online buckle.evenflo.com

First Choice Model 3604098 made 1/16/09 - 9/29/09. **Problem:** Mandatory information may be missing from product labels. **Call:** 800-233-5921 for replacement labels.

Convertible Seats

- **Momentum 65 (LX and DLX)** Models beginning "385" made 3/4/13 - 8/26/13.
- **Sure Ride DLX** Models beginning with "371" made 6/20/12 - 10/17/13.
- **Titan 65** Models beginning "371" made 6/20/12 - 10/17/13.

Problem: Harness buckle may become stuck in latched position making it difficult to remove child. For new buckle **call:** 800-490-7591 or **order** www.buckle.evenflo.com

Combination Seats

- **Chase, Chase LX & Chase Select** Models beginning "306" made 8/23/11 - 3/3/14
- **Chase LX and DLX** Models beginning "329" made 8/23/11 - 3/3/14.
- **Secure Kid (LX, DLX, 100, 300, and 400 models)** beginning "308" made 12/13/11 - 3/3/14.
- **Symphony 65, 65E3 (LX and DLX)** Models beginning "345" or "346" made 10/2/12-8/26/13.
- **Maestro and Maestro Performance** models beginning "310" made 8/22/11 - 10/17/13 have buckle recall (below) AND **Maestro** Model numbers beginning "310" made 11/24/09 - 4/9/10 also have

Problem: Harness buckle may become stuck in latched position making it difficult to remove child. **Call:** 800-490-7591 to order new buckle at buckle.evenflo.com
Problem #2: In a crash, crack may form at front of seat causing child not be properly restrained. **Call:** 800-233-5921 for reinforcement kit. Children weighing less than 40 lbs. should use another seat until repaired; those weighing more than 40 lbs. may continue use only as a booster until repaired.

Evolve Models 34411700 and 344117421 made before 2/9/16 when used with harness. **Problem:** Child may reach button and loosen harness. If child loosens harness stop using seat until remedy is installed. **Call:** 800-233-5921 or **order** remedy kit evolve.evenflo.com

5/3/2018

Transitions Models 34411686, 34411695, and 34411029, made 12/18/14 - 1/29/16 when used with harness. **Problem:** Child may reach button and loosen harness. If child loosens harness stop using seat until remedy is installed. **Call:** 800-233-5921 or **order** remedy kit transitions.evenflo.com

Booster Seats

Big Kid Model 30911173AD, 3091967AD, 30911118AD & 30911120D. **Problem:** Between 8/6/12 - 9/18/12 a small number of seats --meeting all crashworthiness standards--but intended for display--were incorrectly shipped to institutional customers. Affected units have a label stating: "Display Only," Not intended for sale" on back of headrest. **Call:** 800-233-5921 for instruction manual, registration card & label.

Exo Motion (See Recaro)

E-Z-On Products (No Recalls)
800-323-6598 ezonpro.com

First Years (See Tomy)

Fisher Price (See Britax)

GoBooster (No Recalls)
888-327-4336 gobooster.com

Goodbaby USA (See Evenflo)
844-543-2020 gbchildusa.com

Graco 800-345-4109
gracobaby.com

Infant Seats

- **SnugRide & SnugRide Classic Connect** made 3/1/11 - 5/31/13.
- **SnugRide 30 & SnugRide Classic Connect 30** made 7/1/10 - 1/31/13.
- **SnugRide 35 & SnugRide Classic Connect 35** made 5/1/11 - 1/31/13
- **SnugRide Click Connect 40** made 6/1/12 - 12/31/12.
- **Aprica A30** made 7/1/11 - 4/30/12.

Problem: Some harness buckles can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. For new buckle **call:** 877-766-7470 or **order** online at GracoBuckleRecall.com

Convertible Seats

- **Classic Ride 50** made 10/1/11 - 9/30/13.
- **Cozy Cline, Toddler Safe**

Seat-Step 2
made 1/1/06 - 4/30/10.

- **My Ride 70**
made 5/1/12 - 7/31/13.
- **My Size 70, Size4Me 70, Headwise 70, Headwise 70 with Safety Surround** made 1/1/12 - 7/31/13 (and 8/3/13 as some made after the end date of production were made with the old buckles).
- **Ready Ride 70** made 10/01/10 - 9/30/13.
- **Smart Seat, Smart Seat with Safety Surround** made 12/1/10 - 9/30/13 and 10/9/13, 12/25/13, 1/10/14 (some made after the end date of production were made with the old buckles).

Problem: Harness buckles can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. **Call:** 877-766-7470 **Order** GracoBuckleRecall.com

Classic Ride model 1812930 made 3/1/14 - 2/28/15. **Problem:** Label missing information on instruction book location. For new label **Call:** 800-345-4109 or **email** gracobaby.com/2016LabelRecall

Comfort Sport models 1794333, 1813040 made 3/1/14 - 2/28/15. **Problem** Label missing information on instruction book location. **Call:** 800-345-4109 or **email** gracobaby.com/2016LabelRecall

Extend2Fit model 1954477 made 11/27/15 - 1/20/16. **Problem:** Recline label affixed to wrong location may result in infant too upright or toddler too reclined. Assure all labels including recline label (identifying recline positions 1 - 6 on each side of seat) are not in same language. For new label **call:** 800-345-4109

My Ride 65, My Ride 65 with Safety Surround made 4/1/09 - 7/31/13 and 9/30/13. **Problem #1:** Some harness buckles can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. **Order** replacement buckle online GracoBuckleRecall.com or **call:** 877-766-7470 **Problem #2: My Ride 65 only.** In addition to model numbers & dates listed below, fabric tag on back of harness MUST be labeled 2014/06. Models affected:

- 1908152 made 7/23/14 - 7/27/14
- 1813074 made 6/20/14 - 7/27/14
- 1872691 made 5/16/14 - 8/1/14
- 1853478 made 7/11/14 - 7/27/14
- 1871689 made 7/5/14 - 7/24/14

- 1877535 made 5/26/14 - 7/27/14
- 1813015 made 7/3/14 - 7/24/14
- 1794334 made 5/20/14 - 7/15/14

Problem: Harness webbing does not meet breaking strength. **Order** new harness from Gracobaby.com 2014Harness or **call** 800-345-4109 Seat may continue to be used while waiting for replacement kit.

Ready Ride Models 1924519, 1923520 made 3/1/14 - 2/28/15. **Problem:** Label does not show instruction book location. **Call:** 800-345-4109

3-in-1 Seats

Milestone Models 1910130, 1923980, 1926538, 1926539 made 7/9/15 - 10/9/15. **Problem:** Labels do not have required wording about how to install seat with LATCH or seat belt per FMVSS 213. Recall does not affect safety performance. **Call:** 800-345-4109 for new label.

Combination Seats

- **Argos 70 & Argos 70 Elite** made 5/1/11-7/31/13.
- **Nautilus, Nautilus Elite, Nautilus Plus**, made 10/1/27-7/31/13 (and 8/19/13 as some seats were made using recalled buckles).

Problem: Harness buckle can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. **Call:** 877-766-7470 or use online form to order replacement buckle at GracoBuckleRecall.com

Booster Seats

Turbo Booster Models:

- 1963973 made 3/8/16-4/2/16
- 963974 made 12/22/15-3/30/16
- 1963975 made 12/22/15-3/17/16
- 1963976 made 2/17/16-3/24/16
- 1967886 made 1/13/16-4/5/16
- 1975173 made 3/29/16

Problem: Owner's manual omits instruction to prevent seat from becoming projectile by buckling it when not in use. Seat is still effective to restrain child. Verify your booster is affected then **download missing instructions** <mailto:emailgracobaby.com?subject=2016TurboBoosterRecall> or **call:** 800-345-4109

Harmony

877-306-1001 harmonyjuvenile.com

Big Boost Deluxe Problem: In a crash, seat belt may cause excessive force on child's chest increasing risk of injury. Remedy is still under development. **Call:** customer service: 877-306-1001

hauk Fun for Kids

(No Recalls) 905-455-5888

Immi

(See Safe Guard)

Jané

(No Recalls)

415-824-12371 <http://www.jane.com>

Jeffco Fibres

(No Recalls)

508-673-1001

<http://www.jeffcofibres.com>

JJ Cole

(See Tomy)

Jupiter Industries

(No Recalls) 800-465-5795

jupiterindustries.com

Kiddy

678-377-3309 <http://www.kiddyusa.com>

Combination Seats

World Plus Combination Seat

model 51-100WP made 2/1/12 - 10/5/13 (all models ever produced).

Problem: Buckle tongue on shield may not fully engage leaving child unrestrained. *Affects seat only when used with shield* (not as booster).

Call: Customer Service 855-925-4339 to arrange seat return & reimbursement of full purchase price.

Kids Embrace

(No Recalls)

Recalls)

866-947-3287

Lamaze

(See Tomy)

LaRoche Brothers

(No Recalls) (See Jeffco Fibres)

Learning Curve

(See Tomy)

Lil Fan

(No Recalls)

317-804-9160 <https://lilfan.com>

Lilly Gold

(See Triple Play)

Little Tikes

(No Recalls)

Recalls)

800-321-0183 littletikes.com

Maxi-Cosi

(See Dorel)

Merritt Manufacturing

317-409-0148

<http://www.merrittcarseat.com>

Mia Moda, Inc.

866-642-6632 <https://miamodausa.com>

Infant Seats

Mia Moda Viva and Viva

Supreme Model 5000, 5001, 5050, 5051, 5070, 5071, 5080, & 5081.

Problem: Harness splitter plate on rear of seat has sharp edges & may cut harness or base may crack in crash. In crash child would not be properly restrained. **Call:** 877-546-8437 immediately stop using the seat. Manufacturer will offer refund.

Nania

(See Team-Tex)

Nuna

(No Recalls)

855-686-2872 <https://www.nuna.eu/usa>

Orbit Baby

877-672-2229, <https://orbitbaby.com>

Infant Seats

Orbit Baby Car Seat Bases G2

Bases model ORB822000 with Batch #A0840, A0860 or A0880 made 3/20/13 - 7/20/13. **Problem:**

StrongArm knob may detach or spin without tightening base preventing proper installation. Register seat at Orbit website, then **call:** 877-672-2220 for StrongArm knob repair kit. If seat is not tightly secured then install without base until repaired.

Peg Perego

(No Recalls)

800-671-1701 www.pegperego.com

Phil&Teds

(See Goodbaby)

Goodbaby)

Porsche

(Contact Britax)

Recaro

888-973-2276 recarocs.com

Convertible Seats

Como all models made 11/1/07 - 2/16/09. **Problem:** Harness may not tighten/lock properly. In crash child may not be securely restrained & sustain injury. Inspect seat: Take empty seat & pull on harness adjuster strap to fully tighten harness. Next, pull on both shoulder straps without lifting or pressing harness release lever. If harness straps stay tight, continue using seat. If straps loosen, immediately stop using seat. **Call:** 888-473-2290 for replacement.

- **ProRide** all models beginning with 332.01 made 4/9/10 - 6/9/15.
- **Performance Ride** all models beginning with 33301 made 1/15/13 - 6/9/15.

Problem: Tether may detach from car seat during crash increasing risk of injury to child or other occupants. **Call:** 866-628-4750 or visit <http://us.recaro-cs.com/RIDRecallSept2015>

Signo all models made 11/1/07 - 2/16/09. **Problem:** Harness may not tighten/lock properly. In crash child may not be securely restrained & sustain injury. Inspect seat: Take empty seat & pull on harness adjuster strap to fully tighten harness. Next, pull on both shoulder straps without lifting or pressing harness release lever. If harness straps stay tight, continue using seat. If straps loosen, immediately stop using seat. **Call:** 888-473-2290 for replacement.

Safe Traffic System

(No Recalls) 847-233-0365

www.safetrafficsystem.com

SafeGuard

(No Recalls)

Recalls)

800-586-7839 www.safeguardseat.com

Safeline Kids

(See Tripleplay)

Safety Angel/Safe Start

(No Recalls)

561-732-1233 www.safetyangel.com

Safety Baby

(See Team Tex)

Safety 1st

(See Dorel)

Sammons Preston

(No Recalls)

800-323-5547

performancehealth.com

Simple Parenting

(No Recalls)

862-240-1755

happykidssmartparents.com

Snugli

800-374-3603 snugli.com

Booster Seats

Snugli Booster models beginning "308" made 12/13/11 - 3/3/14.

Problem: Harness buckle may become stuck in latched position making it difficult to remove child. **Call:** 800-490-7591 Order **on-line** buckle.evenflo.com

Summer Infant

(No Recalls)

800-268-6237 summerinfant.com

Sunshine Kids

(See Diono)

Teutonia USA

(No Recalls)

Recalls)

877-838-8664 teutoniausa.com

Tomy International

800-704-8697 tomy.com In 2014 stopped manufacturing car seats.

Tripleplay

646-484-8112

Sit 'n Stroll Model 4002 made 5/5/2008. **Problem:** Harness webbing failed crash testing increasing risk of injury to child. **Call:** 800-829-1625 for repair kit.

Uppababy

(No Recalls)

781-413-3000 www.uppababy.com

Urbini

(See Aria Child)

Volvo

(No Recalls)

800-458-1552 www.volvocars.com